

## PMI 转造级滚珠导丝杆外径及导程对照表

PMI 转造级滚珠丝杆有多元化规格与不同导程精度最大转造长度可提供选购，参考表2~表3。

表2 转造丝杆规格表

丝杆公称 外径Ø	导程														转造丝杆 最大长度	
	1	2	2.5	4	5	5.08	6	10	12	16	20	25	32	40		50
8	●	●	●													1000
10		●														1000
12				●	●			●	●							1500
14				●	●											3000
15					●			●		●	●					3000
16				●	●			●		●						3000
20				●	●			●			●			●		3000
25				●	●/○	●/○		●				●				6000
28					●		●									6000
32					●/○	●/○		●			●		●/○			6000
36								●								6000
38								●			●			●		6000
40					●			●			●			●		6000
50								●			●				●	6000
63								●			●					6000
80								●								6000

●：右旋螺纹 ○：左旋螺纹

注：转造级滚珠丝杆长度与精度所限制，如有其他需求请向本公司电洽咨询

表3 导程精度与最大转造长度对照表

丝杆公称 外径 $\varnothing$ (mm)	导程精度等级( $e_{300}$ ) 最大转造长度(mm)			
	C5	C7	C8	C10
8	-	1000	1000	1000
10	-	1000	1000	1000
12	1500	1500	1500	1500
14	3000	3000	3000	3000
15				
16				
20				
25				
28				
32				
36	6000	6000	6000	
38				
40				
50	6000	6000	6000	
63				
80				